

Airworthiness Directives 2004

I, DAVID ALAN VILLIERS, delegate of the Civil Aviation Safety Authority, acting under subregulation 39.001 (1) of the Civil Aviation Safety Regulations 1998:

- (a) revoke the Airworthiness Directives mentioned in Schedule 1; and
- (b) make, as separate instruments, each Airworthiness Directive mentioned in Schedule 1 and attached.



David Villiers
Delegate of the Civil Aviation Safety Authority

20 December 2004

Note: Each attached Airworthiness Directive is being re-made in exactly the same form as appears in the latest published edition of the Directive.

Schedule 1 Revocation and Remaking of Airworthiness Directives

Eurocopter EC 135 Series Helicopters

AD Name	AD Number
Main Rotor Hub-Shaft	AD/EC 135/1 Amdt 1
Tail Rotor Drive Shaft Bearing Attachment Flange	AD/EC 135/2
Tail Boom Bearing Supports	AD/EC 135/3
Air Conditioning System	AD/EC 135/4
Main Rotor Drive Torque Struts	AD/EC 135/5 Amdt 3
SMD45H Display Systems	AD/EC 135/6
Automatic Engine Control	AD/EC 135/7 Amdt 1
FADEC Fail Warning Light	AD/EC 135/8
Main Rotor Hydraulic Actuators - CANCELLED	AD/EC 135/9