
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC-100/2.

S.L. Industries Commander 100 Series and Volair 10 Series Aeroplanes

AD/AC-100/2

General Modifications

9/2008

Requirement: CANCELLED.

This AD is cancelled on 28 August 2008.

Background: This unique Australian AD, raised in 1968 against Aero Commander Service Letters (SB) No's. 6, 10, 12 and 13, and Service Bulletin (SB) No. 1002, required modifications that included rework of wing tips, replacement of door latches, design changes in wing lift strut and fittings, flap and aileron rigging, installation of nose wheel fairing fin and front spar cap reinforcement.

Compliance was forthwith.

As all affected aircraft would have been modified by now, this AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

17 July 2008