AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC-SNOW/5.

Ayres Thrush (Snow) Commander Series Aeroplanes

AD/AC-SNOW/5 Fin Bracing Wire Fittings - Modification 9/2008

Requirement: CANCELLED.

This AD is cancelled on 28 August 2008.

Background: This AD, raised in 1968 against Aero Commander- Olney Division Service Letter

(SL) No. 48, Rev A, required a modification to replace the upper front fin tail wire brackets and fittings due reports of bracket failure. Compliance was required forthwith. As all affected aircraft would have been modified by now, this AD is no

longer required.

David Villiers

Delegate of the Civil Aviation Safety Authority

18 July 2008